

Fig.1




Fig.2




Fig.3




Fig.4




Fig.5





Fig.6







Fig. 7

Fig. 8







Fig. 11




Fig. 12




Fig. 13





Fig. 14



FOI 50 6228260




Fig. 15



T09T50-020200






Fig. 16



097329-061401

Fig. 17



109T50" 62282260

Fig.18







Fig.19





Surface of III-V Compound  
Compositionally Graded Layer  
After Epitaxy

FIG. 10A



Surface of III-V Compound  
Compositionally Graded Layer  
After Epitaxy and Planarization

FIG. 10B